## Start Here

# Scan One Time Only And Copy for Multiple Numbers

CARR-1243	
-----------	--

\_\_\_\_\_AND\_\_\_\_\_

CARR-1244

CARR-1243, CARR-1244

1924,1931

Lumber Sheds

Public

Springfield Hospital Center

Sykesville

The two lumber sheds are one story frame structures located south of the powerhouse. Resting on a concrete foundation, the structures display a gable roof. The lumber sheds measure ten bays long and two bays wide.

#### Maryland Historical Trust State Historic Sites Inventory Form

Survey No. CARR-1243 CARR-1244 Magi No. 07/2434739 DOE \_\_yes \_\_no

1. Nan	<b>1e</b> (indicate pr	referred name)		·
historic	Lumber Shed #1 & #2			
and/or common				
2. Loca	ation <sub>Springf</sub>	ield Hospital Cente	r	
street & number				not for publication
city, town Syke	esville	vicinity of	congressional district	6
state Marylar	nd	county <sup>6</sup>	Carroll	
3. Clas	sification			
Category district _X_ building(s) structure site object	Ownership  public private both Public Acquisition in process being considered not_applicable	Status  occupied  unoccupied  work in progress Accessible  yes: restricted  yes: unrestricted  no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation wonder: Hospital
4. Own	er of Prope	rty (give names a	nd mailing addresses	s of <u>all</u> owners)
name D	Department of Health	n and Mental Hygiene	2	
street & number	201 West Preston S	Street	telephone no	.:301-225-6816
city, town Ba	ltimore	state	and zip code Maryla	and 21201
5. Loca	ation of Leg	al Description		
courthouse, regis	stry of deeds, etc. Carrol	ll County Courthouse	Annex, Rm G-8	liber
street & number	55 Nor	th Court Street		folio
city, town Wes	tminster		state	Maryland 21157
6. Repr	esentation	in Existing	Historical Surve	
`itle				
date			fodoral	
depository for su	rvey records		federal state	county local
city, town			state	

#### 7. Description

Survey No. CARR-1243 CARR-1244

s *	· · · · · · · · ·

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The two lumber sheds, situated in a vertical line, are located south of the powerhouse. The lumber shed to the north is the older structure of the two and is identified as lumber shed #1. The shed to the south is the second lumber shed. The two wooden structures are very similar in appearance so that one description will suffice for both. The structure measures ten bays long and two bays wide and rests on both a cement foundation and cement piers. Rising one story, the building displays a shingled, gable roof. The structure faces east and it is the east side which is open and reveals the ten storage bins. The bins are closed off by hinged doors of wooden planks. The profile of the building from the south wall exhibits an unbalanced appearance because the gable roof on the east side is attached at the crest but hangs down somewhat independently, only supported by rafters due to the absence of the east wall.

₃riod		_	Check and justify below	Survey No. CAI	RR-1244
1400 1500	⊢1599 ⊢1699 ⊢1799 ⊢1899	archeology-prenist archeology-historic agriculture x architecture art commerce communications	oric community planning c conservation economics education engineering exploration/settlemen industry invention	landscape architecture   law   literature   military   music   philosophy   politics/government	science sculpture _X social/ humanitarian theater
Specific	dates	1924,1931	Builder/Architect Hos	pital Personnel	
check:	ar	cable Criteria: ad/or cable Exception:		EFG	
	Level	of Significance:	nationalstate	<sub>X</sub> local	en de la companya de La companya de la co
Prepare support		a summary paragra	ph of significance and	a general statement	of history and

8. Significance

The two lumber sheds are located in the industrial group where support functions for the hospital are housed. The earliest known date on the first lumber shed is 1924. The second shed was constructed in 1931 during a phase of hospital improvement. While neither shed is architecturally superior, the two structures moderately contribute to the built environment of the hospital as a representatives of the outbuildings necessary to keep the hospital operating efficiently.

10. Geog	graphical Data					
Quadrangle name _	lo NOT complete UTM refere	ences		Quadran	gle scale	
Zone Easting	Northing	BZo	ne Eastir	ng l	Northing	
C		D				
Verbal boundary o	description and justification					
List all states and	counties for properties overla	ipping state o	r county b	oundarie	<b>s</b>	
state	code	county			code	
state	code	county			code	
11. Form	Prepared By					
name/title	Lauren L. Bowlin					
organization	Office of Planning, DHM	H	date 6/	86	······································	
street & number	201 West Preston Street	· ·	telephon	<b>e</b> 301–22!	5-6816	
city or town	Baltimore		state Ma	ryland 2	21201	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438



CARR-1243
Lumber Shed #1
Springfield Hospital Center
Sykesville, Maryland
Don Jewell, 6/86
Negatives at MHT
East



CARR-1244
Lumber Shed #2
Springfield Hospital Center
Sykesville, Maryland
Don Jewell, 6/86
Negatives at MHT
East

### End Here

## Scan One Time Only And Copy for Multiple Numbers

<u> ('ARR-124</u> ;	3
AND	

CARR-1244